## Federal Aviation Administration

### MAJOR REPAIR AND ALTERATION (Airframe, Powerplant, Propeller, or Appliance)

Form Approved OMB No. 2120-0020	PALL
For FAA Use	Only

Office Identification

NE-FSDO-03

INSTRUCTIONS: Print or type all entries. See FAR 43.9, FAR 43 Appendix B, and AC 43.9-1 (or subsequent revision thereof) for instructions

forle	gop anci Nebberti	on of this form. i violation (Sec	i his report is required tion 901 Federal Aviat	by law ion Ac	/ (49 L t of 19	J.S.C. 1421). Fa 958).	ilure to re	port can result in a	civil pena	Ity not to exc	eed \$1,000
<del></del>	-	Make	-				Model		<del></del>		
1. Airc	raft		lorcraft		•			BC12-D			
		Serial No.	8727					ty and Registration	n Mark		
		Name (As sho	own on registration cer	tificate	<del>)</del>		Address	(As shown on regi	stration c	ertificate)	
2. Owr	ner	GARA	BEDIAN, JOHN	H				24 FAIRVI			2
	Tho c	Heration idea	tified herein compl	es wi	113.1F	gr FAA Use Or	ıly				
	applic prove confo Section	cable airworth d for the aboration of the airworth of the	hiness requirements ove-described aircraft on by a person author	end t, sub	is ap ject f	o- o					
	/ D	até	Signature of FAA		4. L	Init Identificati	on			5. Type	
·U	nit		Make		•	Model		Serial No	•	Repair	Alteration
AIRFRA	ME		···············(/	As des	cribed	in Item 1 abov	.e) mir				Х
POWER	PLANT									•	•
PROPE	LLER							,	-		
APPLIA	NCE	Type Manufacturer									
<del></del>					6. Co	nformity Stater	nent			<del></del>	
A. Age	ency's N	ame and Addre	ess		B. I	Kind of Agency			C. Certi	ficate No.	
		PHIPPS			X	U.S. Certificated					
		EGON RD.				Foreign Certific Certificated Rep			1-	7542172	78.5
S(	OUTHE	BOROUGH,	MA 01772		<del>                                     </del>	Manufacturer	airStation			7542172	AGE
			nd/or alteration made to rdance with the requir and correct to the best			dentified in iter	n 4 above : S. Federal	and described on the Aviation Regulation	he reverse ons and th	or attachme	nts hereto nation
Date	•	7/3/95			Sig	nature of Autho	rized Indi	vidual			
٠.,	<del></del>	· · · · · · · · · · · · · · · · · · ·				1000/6	refil				
Purs	uant to	the authority o	ivan paragna angellie			al for Return To					
Adm			given persons specifie I Aviation Administrati	on and	w, the	APPROVE	in item 4	EJECTED	the man	ner prescrib	ed by the
BY -		Flt. Standards ector	Manufacturer	V	Insp	ection Authoriza	ation	Other (Specify)			
	l	Designee	Repair Station		Pers Cana	on Approved by ada Airworthine	Transport				
		al or Rejection	Certificate or Designation No.		Sign	ature of Autho	)	vidual		· · · · · · · · · · · · · · · · · · ·	
	rm 337	···	1695670	<i>'</i> .	L_,	Howard J. F.	J. with.	₹.			
MA PO	nm 337	12-881				( )	- (	,			

### NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

### 8. Description of Work Accomplished

(If more space is required, attach additional sheets. Identify with aircraft nationality and registration mark and date work completed.)

Installation of Jasco Alternator system #6555 for Continental engines.

The system consists of a Jasco alternator model #6560T, a Jasco controller model #J12M20SP, and #6540-6555 installation instructions.

- 1) Removed existing generator (Delco-Remy #1101876) from engine.
- 2) Installed Jasco Alternator System #6555 in accordance with Jasco #6540-6555 installation instructions. Skytronics STC # SA971WE (Cessna 150) used as a guide only.
- 3) Located circuit breakers specified, Potter/Brumfield P/N's W23X1A1G-10 and W23X1A1G-50 on instrument panel with other aircraft circuit breakers located 2" to the left and 2" above the right control column. Located circuit breaker/switch, Potter/Brumfield P/N W31X2M16-5 for the field in the center of the instrument panel 2" from the bottom edge with the other aircraft switches.
- 4) Identified circuit breakers and circuit breaker/switches with placards.
- 5) Located controller on the foward side of the firewall 10" in from the right side and 9" up from the bottom.
- 6) Located cold air inlet to blast tube in the left front cowl cutout 2 1/2" to the left and 1" down from the cold air inlet for the cabin heat.
- 7) In accordance with note #4 on the wiring diagram a 10 amp Potter/Brumfield P/N W23X1A1G-10 circuit breaker was used because of the corresponding 18AWG wire used.
- 8) System operationally checked OK. ''r
- 9) Jasco installation instructions attached.





POST OFFICE BOX 807
227 OREGON STREET
EL SEGUNDO. CALIF.

[ZIP CODE - 90245]
PHONE [213] 772-3231
T E L E X 653-454

### JASCO ALTERNATOR SYSTEM "E" & "C" SERIES

### CONTINENTAL ENSURES

### MODEL 6560T 12 VOLT 50 AMP

### INSTALLATION INSTRUCTIONS

STC No. SA999WE Beech 35 "A" thru "G" and 35 "R"

STC No. SA971WE Cessna - 150 - 170 - 172 - 175

STC No. SA1246WE Navion and Navion "A"

- 1. Remove RH magneto, tach shaft adapter, generator and gaskets from the rear accessory case.
- 2. Remove drive gear assembly from your generator and install on alternator shaft, provided parts are in servicable condition. If any parts need replacement the following parts are available from your Continental distributor:

...352029 each Hub 1 each: 352030 ... Retainer 626543 2 each Bushing Rubber each 530412 Nut 2501 Cotter Pin 1 each Gear-Drive each 530997

- 3. Note: It may be necessary in engines with Thompson TF1900 fuel pumps to loosen the four mounting nuts and let the fuel pump drop slightly in order to install the alternator. If governor drive adapter is installed under pump, on Bonanza with hydraulic prop, some metal may have to be removed from govenor drive adapter flange nearest alternator to provide clearance.
- 4. Install the alternator alinging the cutout in the housing with the tach shaft drive adapter. Install with new mounting pad gasket.
- 5. Install tach drive adapter and shaft, and safety wire in an approved manner.
- 6. Install RH magneto and time with engine.


- 7. Install air blast tube to the alternator. Be sure induction end is directed to unobstructed slip stream. Good alternator cooling is a must. The 6560T Alternator is equipped with a 2" blast cover opening, as opposed to 1" as used on the earlier model. This improves cooling which is important especially in long engine idle periods.
- 8. Tighten fuel pump nuts.
- 9. Disconnect electrical wiring from generator voltage regulator and remove the voltage regulator from its present location.
- 10. Install JASCO J12M20 Voltage Regulator and SVP-3 Voltage Peak Protector in coolest possible area. It is suggested that the regulator have 1/4" flat spacers placed between mounting surface and regulator to allow for air circulation.
- 11. For electrical hookup, refer to electrical schematic for voltage regulator and voltage protector wiring and splices to alternator (see wiring schematic).
- 12. All workmanship and material to be in accordance with FAR43-13-2.
- 13. With alternator (generator) switch off, start the engine and operate at normal run speed after activating switch to on position. Check rpm's and ammeter for proper operation of the alternator.
- 14. Recheck and inspect the entire installation. Complete any necessary forms, make log book entry and add to the aircraft equipment list.
- 15. Correct drive Coupling Assembly.


Assembly of the Continental Gear Drive to the 6560T Alternator must be accomplished without undue crush applied to the rubbers blocks (626543 Bushings). The tolerance accumulation of the Drive parts and Alternator Shaft and Internal parts can amount to over .040". When the Drive Assembly is installed a wide range of preload could be applied to the rubber blocks including extruding them out behind the gear.

Skytornics suggests a preload on the rubber blocks of .005 to .008". This can be accomplished as follows; Assemble the Hub Rubber Blocks, Gear & nut on the shaft, leaving out the retainer (668-2) which is .031 thick. Measure the clearance between the rubber blocks and the gear with a feeler gage. Subtract this figure from the retainer thickness (.031) and this will be the preload when the retainer is installed. If it is greater than .005 - .008 machine the backside of the coupling, the difference between the above calculated figure and the correct preload.

DRIVE ADAPTOR AIRBLAST AT O'CLOCK POSITION. DIMPLE IN HOUSING PROVIDES CLEARANCE FOR GOVERNOR ALTERNATOR IS DESIGNED TO BE INSTALLED WITH THE Donanga -

USING SKYTRONICS LARGE DIAMETER SHAFT COUPLING SLEEVE, P/N 530407 (NOT SHOWN) IN GEAR DRIVE ASSEMBLY IS DELETED WHEN





7	6	5	4	3	2	1	ITEM
	1	ĩ	1	2	1	1	атү
352066	2501	530412	530997	626543	352020	352029	CONTINENTAL PART NO
GASKET	COTTER PIN	NUT 5/16 -24	GEAR DRIVE	BUSHING, RUBBER	RETAINER	HUB	DESCRIPTION

MODEL 6560T - Cont.

Page 3

Care must be taken on assembly that the rubber blocks are placed correctly in the retainer. The radii on the blocks are towards the bottom corner of the retainer and against the tongue of the gear. It is important that the nut be adequately tightened against the shoulder of the shaft. If the cotter key hole will not line up then shims must be placed behind the nut to accomplish this.

# HELICOPTER APPLICATION

ROUTE AIR COOLING DUCT TO COOLING SHROUD: SUPPORT DUCT TO PREVENT OBSTRUCTION TO. AIR FLOW.


# FIXED WING APPLICATION

ROUTE RAM AIR COOLING DUCT TO RAM AIR COOLING INLET: SUPPORT DUCT TO PREVENT OBSTRUCTION TO AIR FLOW.


COOLING INLET SHOULD BE EXTERNAL TO AIRCRAFT ENGINE COMPARTMENT AIR. IT IS RECOMMENDED TO PROVIDE A SEPARATE AIR SCOOP INLET TO RAM AIR COOLING DUCT. (DO NOT CONNECT TO HEATER BOX.)

### CAUTION

DO NOT OPERATE ALTERNATOR WITHOUT SUPPLYING ADEQUATE COOLING AIR TO THE ALTERNATOR. OPERATING ALTERNATOR WILL DAMAGE ALTERNATOR WITHOUT ADEQUATE COOLING WILL DAMAGE ALTERNATOR. OPERATION OF ALTERNATOR WITHOUT ADEQUATE COOLING VOIDS WARRANTY.



TYPICAL COOLING FOR JASCO ALTERNATOR




|--|

	DATE 12/22/18 DWN. BY HP	DWN. BY HE
ANI ENIOR		
	SCALE	APPR. BY JES
157	DHEMBON TOLENANCE T. OOB UNLESS OTHERWISE SPECIFIED	B UNLESS OTHERWISE SPECIFIED
RECOMMENDED COOLING FOR JASCO ALTERNATOR	R JASCO ALTERN	NATOR
TNSTALLATION		

5016

DWG. NO.



area of	12-21-93	CLARIFICATION OF WIRING DIA-12-21-93		
APPR	DATE	DESCRIPTION	LTR	
		REVISIONS		

GRAM, FOR J12M2OSP

2 RECOMMENDED. 50 AMP CIRCUIT BREAKER NOT SUPPLIED. POTTER-BRUMFIELD P/N W23X1A1G-50

ω FOR SINGLE WIRE ROUTING USE 8 AWG PER MIL-W-5086: FOR CONDUIT OR BUNDLE ROUTING USE 6 AWG, MIL-W-5086 OR EQUAL AIRCRAFT QUALITY WIRE.



REGULATOR CIRCUIT IS TO BE PROTECTED IN WITH CIRCUIT BREAKER OR FUSE LOCATED IN SIZE IN ACCORDANCE WITH THE FOLLOWING: IN COMPLIANCE WITH FAA REGULATIONS, CLOSE PROXIMITY TO BUSS. FUSE OR BREAKER

16 GA	18 GA	0	22 GA	WIRE SIZE
15 AMO	10 AMP	7.5 AMP	5 AMD	CKT BKT
10 AMP	10 AMP	5 AMP	5 AMP	FUSE

CIRCUIT BREAKER OR FUSE ASSEMBLY NOT SUPPLIED.

Ç: NEW VOLTAGE REGULATOR P/N J12M2OSP THE J12M20 AND THE SVP-3 UNITS. CEEDS AND OBSOLETES BOTH SVP-3. THUS, THE J12M2OSP SUPER-INCORPORATES THE VOLTAGE PROTECTOR

## FAA APPROVED

DEC 2 & 1993

AIRCRAFI CERTIFICATION OFFICE INITIALS:

INSTALLATION WIRING FOR 12V.

50A. NEG GND ALTERNATOR

1001

SHEET 2

<u>Б</u>

KYTRONICS, INC.	C. SEGUNDO, CALIF	
	SEGUNDO, CALIF	
MATERIAL	DATE 12-21-93	DWN. BY C . PACC.
SPEC.	SCYLE	APPR. BY CALLED .
FINISH   DIMENSION TOLERANCE	DIMENSION TOLERANCE	J. wood
		•

•

•

SEP 1 4 1955

U. S. DEPARTMENT OF COMMERCE	Form Approved. Budget Bureau No. 41-R041.5,
APPLICATION FOR AIRWORTHINESS CERTIFICATE AND/OR ANNUAL INSPECTION OF AN AIRCRAFT	INSTRUCTIONS Please print or type. Submit this form to the Civil Aeronautics Administration Aviation Safety Field Representative.
1. TYPE OF APPLICATION (Check which)	Fleid Representative.
■ □ ORIGINAL ISSUANCE OF CERTIFICATE d. □ RECER	ITIFICATION UNDER THE PROVISIONS OF CAR 8 PLE CERTIFICATE UNDER THE PROVISIONS OF CAR 8
<ol> <li>AIRWORTHINESS CLASSIFICATION (Check appropriate item(a))</li> <li>It is requested that the Certificate of Airworthiness be issued to permorthiness classification(s):</li> </ol>	nlt operation of the aircraft in the following air-
a ☐ STANDARD (NORMAL, UTILITY, ACROBATIC, TRANSPORT CATEGORIES) b. ☐ LIMITED (SEE CAR 9)	
e RESTRICTED (SEE CAR B)	
(Check the restricted special purpose operation(s) to be conducted)	
☐ AGRICULTURAL AND PEST CONTROL ☐ PATRO ☐ AERIAL ADVERTISING ☐ FORES	
	T AND WILDLIFE CONSERVATION  ER CONTROL
☐ GLIDER TOWING ☐ OTHER  d. ☐ EXPERIMENTAL	
d. [] EXPERIMENTAL  (Check the type of experimental operation(*) to be conducted)	
☐ RESEARCH AND DEVELOPMENT ☐ RACING	<b>.</b>
☐ AMATEUR-BUILT ☐ EXHIBI	· · · · · · · · · · · · · · · · · · ·
☐ DEMONSTRATION ☐ OTHER	
3. AIRCRAFT IDENTIFICATION (Complete all Items)	
H. AIRCRAFT MAKE b. AIRCRAFT MODEL	c. AIRCRAFT SERIAL NO.
Taylorcraft BC12-D	6727
d, ENGINE MAKE & ENGINE MI	ODEL.
Continent.1	
4. AIRCRAFT REGISTRATION INFORMATION (Complete all tiens)	
a. REGISTERED OWNER'S FULL NAME b. PERMANEN	T MAILING ADDRESS c. AIRCRAFT NATIONALITY AND REGISTRATION MARK
	AND REGISTRATION MARK
William Funford 28 Pag	cack road,
	cack road,
	cack road,
	cack road,
Park )	ecack road, lidge, N.J. N- 96427
	the aircraft identified in Item 3 above which is he Regulations of the Administrator, Part 501 in:

36 OCT 10 1963

Form ACA-305 (11-51)

U. S. DEPARTMENT OF COMMERCE CIVIL AERONAUTICS ADMINISTRATION AIRCRAFT INSPECTION REPORT (To be completed by a CAA representative or approved repair station) The aircraft described in Item 3 on the reverse of this form has been inspected and found to conform to the following: (Check and complete applicable terms)

1. AIRCRAFT AND ENGINE CERTIFICATION BASIS

a. 
AIRCRAFT SPECIFICATION NO. 500 THE THROUGH SHEET REVISION NO b. AIRCRAFT LISTING PAGE NO. c.  $\square$  airworthiness directive summary 1955 to (Cerr) .  $\square$  civil air regulation part 8 (modified type certificate) 2. AIRCRAFT AND ENGINE OPERATING RECORDS . AIRCRAFT NEW-NO PREVIOUS OPERATION OR MAINTENANCE HISTORY b. E COMPLIANCE WITH APPLICABLE AIRWORTHINESS DIRECTIVES RECORDED c. TAIRCRAFT RECORDS INDICATE THE AIRFRAME HAS BEEN OPERATED A TOTAL OF 1487: 15 d. T ENGINE RECORDS INDICATE THE FOLLOWING OPERATION: TOTAL HOURS \_\_1427:15 SERIAL NO.3804468 SERIAL NO. TOTAL HOURS SERIAL NO. TOTAL HOURS SERIAL NO. TOTAL HOURS 3. PREVIOUS INSPECTION RECORD (INSPECTION RECORDED ON FORM ACA-319) a. LAST AIRWORTHINESS INSPECTION CONDUCTED AUTOM BY AIRCRAFT MANUFACTURER BY APPROVED REPAIR STATION, CERTIFICATE NO. M BY MECHANIC, CERTIFICATE NO. 342614 ASE b. PERIODIC AIRCRAFT INSPECTION REPORT, FORM ACA-319, WAS RETURNED TO OWNER 4. AIRWORTHINESS DOCUMENTS ISSUED OR REVIEWED a. OPERATION LIMITATIONS. FORM ACA-309, WAS ISSUED (COPY ATTACHED) 55 PH b. CURRENT OPERATION LIMITATIONS, FORM ACA-309, IS AVAILABLE IN AIRCRAFT c. CURRENT APPROVED AIRPLANE FLIGHT MANUAL IS AVAILABLE IN AIRCRAFT d. CURRENT WEIGHT-AND BALANCE INFORMATION IS AVAILABLE IN AIRCRAFT e. [7] THIS INSPECTION HAS BEEN RECORDED IN THE AIRCRAFT RECORDS FINE INSPECTION.

1. CERTIFICATE OF AIRWORTHINESS, FORM ACA-1362, ISSUED TO EXPIRE ADJUST AT 10-5 (DATE)

1. PREVIOUS FORM ACA-1362 WAS ISSUED TO EXPIRE ADJUST AT 10-5 (DATE)

1. OPT. B A. Sted TREET

(DESIGNATION NO.) 5. CAA APPROVED REPAIR STATION CERTIFICATION The aircraft described on the reverse has been inspected under the authority accorded certificated repair station \_ by CAR 52 and was found to be: AIRWORTHY UNAIRWORTHY (REPAIR STATION AUTHORIZED SIGNATURE)

I HAVE INSPECTED THE AIRCRAFT DESCRIBED ON THE REVERSE AND FOUND IT AIRWORTHY (Check appropriate term)

DESIGNATION NO

3440

8/24/55

9-15-55

Reg. 1 NY

H. S. GOVERNMENT PRINTING OFFICE 10 40092

6. CAA REPRESENTATIVE CERTIFICATION

Form ACA-805a (11-51)

ACCEPTED ...

SPOT CHECKED