| NG | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | **Description of Inspections, Tests, Repairs and Alterations**<br>Entries must be endorsed with Name, Rating and Certificate Number of Technician or R<br>Facility. (See back pages for other specific entries.) |
|---|---|---|---|
| | | | 12-17-2010 New parts installed in Continental A75-8 sn# 3528558 |
| | | | 1.-SA646538 A65 / A75 gasket set. |
| | | | 8.-21608 cam follower bodies. |
| | | | 1.-4546 camshaft. |
| | | | 1.- 530213 / 24804 connecting rod bolt set. |
| | | | 1.-+015 five ring piston ring set. |
| | | | 4.-A25127 Piston pin / pin plug. |
| | | | 1.-356/4213431/21160/2450 oil pump kit. |
| | | | 1.- crankshaft seal taper. |
| | | | 1.- 40237. +010 bearing set. |
| | | | 4.- 4638 Pistons 5 ring. |
| | | | 4.- 657512 Intake valves. |
| | | | 4.-655972 Exhaust valves. |
| | | | 4.- A 35159A1 connecting rods. |