



All measurements in inches



Pulley hole
Diam measured
0.385

Steve Stearns 22 Aug '15 Rev1 As measured