

# TAYLORCRAFT



## AVIATION CORPORATION

14600 COMMERCE N. E.

P. O. BOX 243

ALLIANCE, OHIO 44601

Apr. 1 '80.

Fran Uteg  
503 Washington, Dr.  
Fairhope, Ala. 36532

Dear Fran:


The sketch inclosed contains dim's. that you requested. All Dims are to center line of the tubing. Unless otherwise stated the fittings fall on center line of tubing.


To align the fuselage the top motor mount bolts should be leveled, the front and rear wing butt ftg's should then be level and also the front and rear stab. attaching points must be level laterally with front mount bolts.

Hope this will help you.

Sincerely,

*John H. Svoboda*  
John H. Svoboda.  
Plt. Mgr.





ALL MODEL B TAYLORCRAFT

BOTTOM - TOP VIEW

STATION NUMBERS ARE FOR REFERENCE ONLY